

TITLE 267 – NEBRASKA OIL AND GAS CONSERVATION COMMISSION

CHAPTER 3 – DRILLING, DEVELOPMENT, PRODUCING AND ABANDONMENT

007 FORM 6 - PLUGGING RECORD

If any well is plugged or abandoned, a record of work done must be filed on Form 6 with the Director within thirty (30) days after the work is completed. The report shall give a detailed account of the manner in which the abandonment or plugging work is carried out, including the nature and quantities of materials used in plugging and the location and extent (by depths) of the plugs of different materials; records of the amount, size and location (by depths) of casing and junk left in the well, and a detailed statement of the volume and weight of mud fluid used. Upon written request, geological information will be kept confidential for twelve (12) months after the filing thereof unless written permission to release the information at an earlier date is obtained from the operator.

